



Progress in factories producing for H&M (as of 1st. of December 2017)

Total number of findings in factories




The total number of findings is increasing due to follow-up inspections and new added factories.


Percentage of the total findings in factories




Total Number Of Original Issues Which Are Noted In Intial Assesments



Percentage of the Original findings in factories



Percentage of specific findings in total 276 factories (as of 1st. of December 2017)



No progress: The factory has not yet taken action to address finding

In design phase: System design awaiting approval

Letter of credit opened / installation in progress: Factory has made an official agreement with material supplier and completed payment agreement / installation in progress according to remediation plan

Compliant: No further actions required by Accord